

Play Inspection Report Findings – Summer 2019

Play Area	Item	Repair Required	Risk Rating
Wymer Drive	Entrance Gate	Entrapment on side of gate	Medium
	Play Tower	Caps Missing on Posts	Medium
	Swings	Wear to chains	Low
	Trampoline	Surface is wearing	Low
Mileham Drive	Signage	Rotten Post	Low
	Play Tower	Surface Shrinkage	Medium
Mileham Drive MUGA	Swings	Wear to chains	Low
	Waste Bin	Parts Missing	Low
St Michaels – Large Area	Gate	Loose Fixings	Low
	Fencing	Some Damage to monitor	Low
	Waste Bin	Liner Not secure	Low
	Information Signs	None Present	Very Low
	Roundabout	Gaps to monitor	Low
		Wet Pour Lifting	Low
	Multi Play	Bolt Caps Missing	Very Low
		Loose Fixings	Low
	Swings	Does not meet current requirements – monitor	Very Low
	Activity Trail	Tree canopy too low	Low
		Splits – monitor	Low
		Surface Eroded	Low
		Loose Fixings	Low
	Waste Bin	Liner Not secure	Low
		Bin Full!!	Low
	Seat	Overgrown Foliage	Low

St Michaels – Small Area	Entrance	Thorny Foliage	Low
	Belly Swing	Mats silted up	Low
	Multi Play	Finger Entrapments	Very Low
		Algae	Low
		Bolt Caps Missing	Very Low